## Partial Translation of Publication S52-35629

A die for use in forming (hereinafter as D) includes a large inner diameter portion 1, a conic portion 2 having two stepped taper surfaces 2a and 2b, and a small inner diameter portion 3 formed in a continuous manner. As shown in Fig. 2, an upper taper surface 2a of the conic portion 2 connected with the large inner diameter portion 1 is set to have less than 45° taper angle  $\alpha$  in the direction of a centerline of the die D. A lower taper surface 2b of the conic portion 2 connected with the small inner diameter portion 3 is set to have a taper angle  $\beta$  smaller than the abovedescribed taper angle  $\alpha$ , in the direction of the centerline. The abovedescribed taper angle  $\alpha$ , which is changed according to thickness and drawing rate (reduction ratio of the diameter) of a pipe to be processed, it is usually set within the range of 30-45°. Meanwhile, the above-described taper angle  $\beta$ , which is set approximately 10° smaller than the abovedescribed taper angle  $\alpha$ , that is, to be less than  $35^{\circ}$ , is set in accordance with the taper angle  $\alpha$ . If the taper angle  $\alpha$  is more than 45°, the small diameter portion of a formed stepped pipe is not drawn to more than 30mm and collapses take place in the area from the conic portion to the large diameter portion when the processed pipe is pushed into the die D. If the taper surface of the conic portion is tilted less than 45° constantly. the small diameter portion is drawn more than the case above described. However, if the small diameter portion is drawn more than 50 mm, collapses take place in the area from the conic portion to the large diameter portion Compared with this, when the taper angle  $\alpha$  is less than 45° and the taper angle  $\beta$  is set to be less than 35°, which is approximately  $10^{\circ}$  smaller than the taper angle  $\alpha$ , the small diameter portion of a formed stepped pipe can be drawn to a desired length.

30

5

10

15

20

25

Moreover, the height H of the above-described conic portion 2, as described later, is determined so as that the diameter of the small diameter portion of a formed stepped pipe is less than 80% of the diameter of the

large diameter portion and the taper angle  $\beta$  is approximately 10° smaller than the taper angle  $\alpha$  and less than 35°. As described above, the conic portion 2 is formed on the two-stepped taper surfaces 2a and 2b and the taper angles  $\alpha$  and  $\beta$  of each of the taper surfaces 2a and 2b are set to be prescribed angles. When a pipe is pushed into the die with prescribed pushing force to form two steps, It is reduced centripetally and drawn downward at the upper taper surfaces 2a of the conic portion 2. Then, the above-described pushing force is sent back to the small inner diameter portion 3 and makes a pipe drawn downward at the lower taper surface 2 of the conic portion. It results in preventing a force to draw a pipe downward from decreasing, making plastic metal flow from the lower taper surface 2b of the conic portion 2 to the upper taper surface 2a smooth and increasing thickness of the stepped portion of pipe smoothly. Consequently, collapse of a pipe in the forming process can be prevented and reduction ratio (drawing ratio) can be increased. Now, a die D and a stepped pipe p along with process steps 1,2....n will be detailed.

5

10

15

20

25

30

As shown in Fig. 3, a raw material pipe po having a prescribed size calculated by volume of a processed stepped pipe is pushed into a large inner diameter portion 1 of the first die D1 (a first reduction process) and thereby a first stepped pipe is formed. When the first compression process is not enough to form a step, if necessary, the stepped pipe P1 formed in the previous process is pushed into the second die D2 where the small inner diameter 3 is formed to be smaller, and the taper angles  $\alpha$  and  $\beta$  of the upper and lower taper surfaces 2a and 2b of the conic portion 2 are set to be somewhat larger. Then, a stepped pipe P2 is formed. If necessary, the above described compression process is repeated as the third or the forth reduction process, so as to form an n-numbered stepped pipe Pn. According to reduction of the small inner diameter portion 3 of the die D for use in every reduction process, the taper angles  $\alpha$  and  $\beta$  and the height H of the conic portion 2 are set so as to reduce the small inner diameter portion 3 of formed stepped pipe. Moreover, in forming a stepped pipe of which reduction may be small, the die Dn in the final reduction process has

little conic portion 2 and a curved surface toward a small inner diameter 3 in a continuous manner. After the above reduction process, a drawn bar 21 is pushed into a small inner diameter through hole 4 of the stepped pipe Pn in the die Dn in the final reduction process, and a drawing process is carried out to draw the stepped pipe Pn. However, some materials such as stainless steel and copper may cause a spring back phenomenon in which finished size of a reduced pipe becomes slightly smaller than size of a die. In such case, drawing process is carried out after a die Dn in the final reduction process is replaced with a die Dn+1 adjusted to the outside diameter of the pipe and the stepped pipe Pn is engaged into a die.

# 19日本国特許庁

①特 許 出 願 公 告

#### 許 公

昭52一35629

60 Int.C12

識別記号 60日本分類 庁内整理番号 **@公告** 昭和52年(1977) 9 月 10日

B 21 C 37/16 B 21 D 51/10

12 C 333 12 C 335 12 C 55

6809 - 396809 - 397518 - 39

発明の数

(全 6 頁)

1

図段付パイプの成形方法およびその装置

願 昭50-49421 204年

23出 願 昭50(1975)4月22日

開 昭 5 1 - 1 2 3 7 6 1 公

④昭51(1976)10月28日

73発 明 深水貞彰

> 神戸市東灘区 森 南 町 3の4の 2 3

包出 願 人 株式会社井上鉄工所

神戸市東灘区本山南町6の1の1

個代 理 人 弁理士 田中清一 外1名

### 

部とが順に連続して形成され、上記円錐部の大径 部へ接続される上段傾斜面の中心線方向に対する 傾斜角が45度以内に設定され、上記円錐部の小 径部へ接続される下段傾斜面の中心線方向に対す ど小さく設定されてなるダイスに対し、上記大径 部の内径と等しい外径を有する原材料パイプをダ イスの大径部より圧入して段付状のパイプに冷間 成形した後、上記段付状のパイプの小径孔内に延 伸棒を圧入して該段付状パイプの小径部を所定長 25 大径部と2段の傾斜面を有する円錐部と小径部と さに冷間延伸せしめることを特徴とする段付パイ プの成形方法。

2 大径部と2段の傾斜面を有する円錐部と小径 部とが順に連続して形成され、上記円錐部の大径 傾斜角が45度以内に設定され、上記円錐部の小 径部へ接続される下段傾斜面の中心線方向に対す る傾斜角が上記上段傾斜面の傾斜角より10度ほ ど小さく設定されてなるダイスを、ダイス支持板 プレスによつて加圧される押圧板を配設し、該押 圧板に、ダイス中心練方向と平行なる固定枠と眩

固定枠内に摺動可能に嵌挿され一端が固定枠から 突出する摺動棒とからなる案内具を介して、上記 ダイスに対し摺動自在に嵌合された突き出し棒支 持板を連結し、該突き出し棒支持板上に上記ダイ 5 ス内に突出する突き出し棒を固定し、上記押圧板 の下面に押圧具又は延伸棒を取外し可能に装着し

2

### 発明の詳細な説明

本発明は、冷間にてバイプ素材を段付バイブに 10 成形加工する方法およびその装置に関するもので ある。

たことを特徴とする段付パイプの成形装置。

一般に段付パイプは農機具のキングピンサポー ター、六角スパナー、ベアリング受等に用いられ てきたが、従来のパイプの冷間成形技術において 1 大径部と 2段の傾斜面を有する円錐部と小径 15 は直径の絞り率は 1 5 %が限度とされ、従来の方 法による型成形においては第7図A,Bに示すよ うに成形品a,bはその円錐部Ta,Tb が長く なり、この円錐部を段付に形成することが至難で あつた。したがつて段部を形成するために大小径 る傾斜角が上記上段傾斜面の傾斜角より10度は 20 のパイプを溶接で接続した製品、または熱間成形 品が使用されていたが、前者は工数がかかり溶接 部が破損し易く、後者は燃料を必要とし酸化皮膜 除去などの工程が必要であるという欠点がある。

本発明は上記の欠点に鑑みなされたものであり、 が順に連続して形成され、円錐部の大径部へ接続 される上段傾斜面が中心線方向に対し 45°以内 の角度で傾斜する一方、円錐部の小径部へ接続さ れる下段傾斜面が中心線方向に対し上記上段傾斜 部へ接続される上段傾斜面の中心線方向に対する 30 面の傾斜角度より小さい角度で傾斜するように設 定されたダイスに、パイプ材を圧入して段付状の パイプを成形した後、この段付状のパイプの小径 孔に延伸棒を圧入して小径部を延伸することによ つて段差の大きい段付パイプを簡単に成形する方 上に取外し可能に固定し、該ダイスの上方に油圧 35 法およびこの段付パイプを多量生産方式で能率的 に加工する成形装置の提供を目的とするものであ

3

以下、本発明の成形方法およびその装置の実施 例について図面に基づいて説明する。

成形に用いるダイス(総称して符号Dで示す) は大径部1と2段の傾斜面2a,2bを有する円 り、第2図に示すように円錐部2の大径部1へ接 続される上段傾斜面 2 a はダイス D の中心線方向 に対して 4 5 度以内の傾斜角 αをもつように設定 され、円錐部2の小径部3へ接続される下段傾斜 り小さい傾斜角々をもつように設定されている。 上記傾斜角αは加工するパイプの肉厚および直径 絞り率(直径縮小率)によつて変更されるが、通 常30~45°の範囲内に設定される一方、上記 即ち35°以内の角度であり、傾斜角αに対応し て設定される。この傾斜角αが45°以上の場合、 加工パイプをダイス Dに圧入しても成形された段 付パイプの小径部は長さが約30㎜以上伸びず、そ スDの円錐部2の傾斜面を 45° 以内の単一の傾 斜面にした場合には成形された段付パイプの小径 部は上記の場合よりも伸びるが、その長さが約 5 0㎜以上になるとその円錐部より大径部に崩れ が生じる。これに対し、傾斜角αを45 $^\circ$  以内と  $^{25}$  どなく小径部 $^{f 3}$ に曲面で連続されたものとなる。 し、傾斜角βを傾斜角αより10°程度小さく 35°以内にした場合には成形された段付パイプ の小径部は所望の長さに伸ばすことができる。

尚、上記円錐部2の高さHは、後述のように成 径の80%以内にとどめることにより且つ傾斜角 αを45°以内に、また傾斜角βを傾斜角αより 10° ほど小さく35° 以内にすることにより設 定される。このように円錐部2を2段の傾斜面 2 a,2 bに形成し、且つこの各傾斜面2a, 2 bの傾斜角α · βを上記のように所定角度に設 定したことにより、段付きを成形すべくパイプを 一定圧で押圧した際、この押圧力によってパイプ には円錐部2の上段傾斜面2 a にて先ず求心方向 に絞る力とともに下方へ伸ばす力が作用し、次に 40 第2圧縮工程で成形された2番段付パイプP2. 円錐部2の下段傾斜面2 b にて上記押圧力を小径 部3側へもどし、主に下方へ伸ばす力となし、こ の下方へ伸ばす力の減少を防ぐとともに、円錐部 2の下段傾斜面2 bより上段傾斜面 2 a へのパイ

プの塑性流動を滑らかにしてパイプの段付部の肉 厚の増大を円滑に行うことができ、よつて、成形 の際のパイプの破壊を防ぎ、且つ縮小率(絞り率) を増大させることができる。以下ダイスDおよび 錐部2と小径部3とが順に連続して形成されてな 5 段付パイプpに工程段数1、 $2\cdots\cdots n$ を附して説 明する。

先ず第3回に示すように仕上り段付パイプの体 積から求めた一定寸法の原材料パイプ po を第1 ダイス D<sub>1</sub> の大径部 1 に圧入(第1圧縮工程)し 面 2 b は同じく中心線方向に対し上記傾斜角 αよ 10 て 1 番段付パイプ P 1 を成形する。第 1 圧縮工程 のみでは段差が充分に成形できないときは必要に よつて、前記小径部3を更に小径に形成し、且つ 円錐部2の上段および下段斜面2 a , 2 b の傾斜 角α·βを前記角度範囲内で第1ダイスD<sub>1</sub>のも 傾斜角 $m{ heta}$ は上記傾斜角 $m{lpha}$ より $m{10}$ 。程度小さく、 15 のより幾分大きく設定した第 2 ダイス  $m{D_2}$  に、前 工程で成形された段付パイプP, を圧入(第2圧 縮工程)して段付パイプP2を成形する。以下必 要によつて第3、第4と同様の圧縮工程を繰り返 しn番段付パイプPn を成形する。各段圧縮工程 の円錐部より大径部に崩れを生ずる。また、ダイ 20 に用いるダイスDの小径部3の縮少に伴い、円錐 部 2 の傾斜角 α · β および高さH を小径部 3 への 絞り込みが可能なように設定する。尚、絞り率の 小さくてよい段付パイプの成形においては最終圧 縮工程(第5図)のダイスDn は円錐部2が殆ん 上記圧縮工程の後、最終圧縮工程のダイスDn 中 にある段付パイプPn の小径孔4に延伸棒21を 圧入して段付パイプPn を延伸する延伸工程を行 なう。ただし、パイプの材質によつてはステンレ 形された段付バイブの小径部の径をその大径部の 30 ス鯛、銅などの材料は圧縮成形の仕上り寸法がダ イスの寸法より若干小さくなるスプリングバック 現象が生じるから、この場合には最終圧縮工程の ダイス Dn をパイプ外径に合せたダイス Dn + L に取り替え、前記段付パイプPnを嵌入して延伸 35 工程を行なう。

> 第1図は電縫管を成形した各圧縮工程および延 伸工程における段付パイプの断面を示し、斜線で 示す部分はダイスDである。第1図Aは第1圧縮 工程で成形された1番段付パイプP1、同図Bは 同図Cは第n圧縮工程で成形されたn番段付バイ プPn であり、同図Dは前記n番段付パイプに延 伸工程を行なつた n + 1 番段付パイプ P n + 1 を 示す。圧縮工程が進むに従い段付パイプの小径部

5

は小径となり、その円錐部の高さは縮小され、小 径部の肉厚は増加する。そして、このような n番 段付パイプPn の小径孔 4を延伸して肉厚を薄く して全長を伸している。

圧縮工程における絞り込みの直径は素材パイプ 5 直径に対して軟鋼の場合は80~85%以内、硬 鋼の場合は90%程度とするのが最適である。ま た、圧縮工程が進むに従い押圧力が増加するから、 ダイスD上部即ち大径部1を高くしてパイプ上部 (パイプの大径部)が押圧力により外側に膨らむ 10 ことを防止する。

次に、成形装置について説明すると、第3図な いし第7図において、 D1, D2, Dn および Dn+1はダイスであり、該各ダイスは上部 6, 6,6,6"と中部7,7,1"とスカート 15 うにする。 部 8 , 8', 8', 8'" に分割され、それらを順に積 重ね、上面より貫通するポルト9,9′,g′,g′′ によって一体に連結してなり、上部6,6,6, 6""には大径部1,1,1,1"、中部7,7,1"、 7''' には円錐部 2 , 2 , 2 , 2 , 2 と小径部 3 , 3 , 20 工程の著しい短縮をはかることができ、且つ段付 3', 3''' とが形成され、各スカート部8, 8, 8,8" は第4図に示すように横断面が半月形状に形 成され、底部をポルト10によつてダイス支持板 11の中央部に左右対向して固定されている。 12はパイプ材押圧具で先端はパイプ内径より1 25 ある。また、本発明装置は、油圧プレス加圧によ m/m小さく形成され、油圧プレス(図示せず) によって加圧される押圧板13の下面中央に取外 し可能に固定されている。14は突き出し棒支持 板であり、スカート部8,8′,8′ル対し摺動 可能に嵌合されている。 15は押圧板 13を上下 30 成形段付パイプの形状を示す断面図、第2図は第 に案内する案内具であつてその固定枠 17の一端 は押圧板13にナット18によつて固定され、ダ イスDの中心線方向に平行に支持され、固定枠 17の内部に摺動棒16が摺動自在に嵌挿され、 摺動棒16の下端は固定枠17の下端に設けられ35る縦断面図、第7図は延伸工程における縦断面図、 た抜け止め手段17aを通して突出し、突き出し 棒支持板14にナット19により固定されている。 20,20,20だおよび20‴はスカート部8, 8', 8''' の間に収納された突き出し棒であつ て、ダイス小径部 3に適合する直径の丸棒とし、 40 縮工程用ダイス、  $D_n+1$  ……延伸用ダイス、 下端部は突き出し棒支持板 1 4 の中央に固定され ている。延伸工程では第7図に示すように押圧具 12を押圧板13より取り外し、延伸棒支持具 22に取り替え、該支持具の下端に延伸棒21を

取り付ける。ダイスDは成形工程毎に取り替える もので、D<sub>1</sub>, D<sub>2</sub>····· D<sub>n</sub>+1 の各種が準備され

各工程における成形完了後の段付パイプを取り 出すには、前記装置の押圧具12または延伸棒 21を抜き上げると、案内具固定枠17の抜け止 め手段17aを介して摺動棒16が引き上げられ、 それとともに突き出し棒支持枠14が上り、突き 出し棒 20 , 20' , 20'' も押し上げられ ることにより、成形パイプP1, ……Pn+1 の 下端を押し上げ、第1図に示す如き成形パイプ P. , ……Pn+1 を取り出すことができる。こ の突き出し棒 20 , 20' , 20'' , 20''' の押し上 げ力が成形の際パイプPに作用することのないよ

本発明は、以上説明したように、パイプ材から 段付パイプの冷間成形をパイプの破壊もなく簡単 に行うことができ、また直径の縮小率(直径絞り 率)を著しく増大させることができるので、成形 パイプを安価に製造することができ、しかも従来 の密接段付パイプ、熱間成形段付パイプなどに比 し材質的に優れ、表面も美くしく、強度もある段 差の大きい段付パイプを得ることができるもので つて安価に能率よく加工できるものである。

# 図面の簡単な説明

図面は本発明の実施態様を示すもので、第1図 AないしDは各圧縮工程および延伸工程における 1図Aにおいて鎖線円で囲んだ部分の拡大図、第 3図は第1圧縮工程における縦断面図、第4図は 第3図のA-A線断面図、第5図は第2圧縮工程 における縦断面図、第6図は第n圧縮工程におけ 第8図は従来例による冷間成形パイプの断面図で

D……ダイス、D1 ……第1圧縮工程用ダイス、 D2 ……第 2圧縮工程用ダイス、 Dn ……第 n圧 Po ……パイプ材、P1 ……1番段付パイプ、 P 2 …… 2 番段付パイプ、 Pn …… n 番段付パイ プ、Pn+1 ……延伸段付パイプ、1,1,,1,, 1‴ ……大径部、2,2,2,2″ ……円錐部、

7

3,3',3',3'' ……小径部、4……パイプの小径孔、6,6',6'' ……タイス上部、7,7',7',7'' ……タイス中部、8,8',8'',8''' ……タイススカート部、9,9',9'',9''' ……ボルト、10……ボルト、11……タイス支持板、12… 5…押圧具、13……押圧板、14……突き出し棒支持板、15……案内具、16……摺動棒、17……固定枠、17a……抜け止め手段、20……突き出し棒、21……延伸棒、22……延伸棒支

8

持具、2 a , 2 a , 2 a", 2 a" ……上段傾斜面、2 b , 2 b', 2 b", 2 b": ……下段傾斜面、α… …上段傾斜面の傾斜角、β……下段傾斜面の傾斜角、H……円錐部の高さ。

### 69引用文献

実 開 昭49-2832

第1図









